

PCN Title Discontinuation of Frozen Firmware Manta CMOS Dual Tap Models

Affected Products **Frozen Firmware** Manta camera models: G-040, G-158, G-223, G-235, G-282, G-283, G-319, G-419, G-505, G-507, G-895, G-917, G-1236, G-1620, G-2040, G-2460

PCN Number PCN2024-08-27 **PCN Issue date** 27.08.2024

Contact [Inside Sales Team](#)

Change Classification

Major

Change Type

Discontinuation

Affected Products

See Annex

Change Description

Due to the discontinuation of a part within the camera, we are forced to make a new revision of the affected camera models. This requires a Firmware change. As the affected item numbers use a specific frozen firmware, we need to discontinue them.

Reason for Change

Discontinued component within the camera.

Impact / Possible Successor

Please get in contact with your sales representative to discuss migrating to a new firmware or last time buy (LTB) demands.

Last Time Buy Date

20.09.2024

The information provided in this product change notification are subject to change without notice.
For the latest version of this document, please visit the Allied Vision [website](#).

Support:In case of technical questions please contact our [Support Team](#)**General inquiries:**Please contact our [Inside Sales Team](#)

Annex**Item no. affected products**

E0020644
E0020720
E0022639
E0020778
E0022752
E0022753
E0022754
E0020740
E0022722
E0020836
E0020835
E0020822
E0020620
E0020828
E0022711
E0022725
E0020568